Richmond Refinery LPS Alert - Safety

Operators sprayed with spent sulfuric acid





IMPACT ERM: 7361

Location: Cracking - Alky

Contact Information:

Doug Fryer 242-2692 DTFR@chevron.com

Reference: Information



Air-driven diaphragm transfer pump showing air exhaust valve (probable source for spent acid spray).

Incident Description:

Two operators were sprayed with spent sulfuric acid while starting an air-driven diaphragm transfer pump on February 7th, 2011.

When the pump was started, a small amount of the spent acid was sprayed into the air and some of that acid landed on the operators. One of the employees received medical attention beyond first aid for some acid that hit the back of his neck. This injury has been classified as a Recordable Injury.

A TapRooT investigation is in progress.

Immediate Actions Taken:

- 1) Both operators received initial evaluation and treatment from CFD EMTs.
- One operator was transported off-site for further evaluation and treatment.



This document is intended for company workforce only. Nothing herein should be construed as a legal determination of causation or responsibility. The company makes no representations or warranties, express or implied, about the thoroughness, accuracy, or suitability of use by others of any of the information contained herein.

Always remember to do your LPSA – because we care about you!